

CORNER RECORD

Document Number 360 (3)

City of _____

County of Merced, California

Brief Legal Description Southeast Corner Section 18, T. 8 S. R. 9 E., M. D. B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 09-12-2013

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1-1/4" Inside Diameter Iron Pipe with unreadable Yellow Plastic Plug down 1.2' set inside 1' diameter monument well.

Map Reference: R.S., Vol. 51, Pg. 36.

A description of the physical condition of the monument as found and as set or reset: Monument was found in good condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 24, 2013

Signed Bradley D. Buller P.L.S or R.C.E. No. L 7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct. 30, 2013

and examined and filed Oct. 31, 2013

Signed J. Steven Reichmuth P.L.S or ~~R.C.E.~~ No. 4895

Title County Surveyor



County Surveyor's Comment _____



TO GUSTINE

SR 33

PK & SHINER
IN UTILITY POLE
W/TELE BOX #29010

SET $\frac{5}{8}$ " REBAR
W/PUNCH MARK
DOWN 0.4'

100.43'

47.80'

GUN CLUB ROAD

FND 1-1/2" IP WITH
UNREADABLE YPP
DOWN 1.2' SET INSIDE
1' DIAM. MONUMENT WELL

PK & SHINER
IN UTILITY POLE

SET PK & SHINER
IN FENCE POST

39.40'

58.86'

TO 15

