


CORNER RECORD

Document Number 1363

City of _____

County of Merced, California

Brief Legal Description S.W. Corner Section 33, T.7S., R.13E., M.D.B.#M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1-09-08

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner – Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablished corner using ties shown on Merced County Corner Record No. 1363 dated March 27, 2008. Original monument destroyed by road construction. See Page 2.

A description of the physical condition of the monument as found and as set or reset: Set 1" (I.D.) Iron Pipe with tag stamped "Merced County Surveyor."

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 1, 2008

Signed [Signature] P.L.S or P.C.E. No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 1, 2008

and examined and filed April 1, 2008

Signed [Signature] P.L.S or P.C.E. No. 4895

Title Dep. County Surveyor



County Surveyor's Comment _____

SECTION 32
T.7 S., R.13 E.

SECTION 33
T.7 S., R.13 E.

CHISELED "X" IN
CONCRETE WINGWALL.

SET 1" (I.D.) IRON PIPE TAGGED "MERCED
COUNTY SURVEYOR" FOR S.W. CORNER
OF SECTION 33 PER 108 PM 28.

DICKENSON

FERRY ROAD

BRIDGE

30'

48.73'

42.90'

30'

43.70'

58.13'

30'

CHISELED "X" IN
CONCRETE WINGWALL.

NAIL & TIN IN S.W.
SIDE OF POWER POLE.
NAIL AND TIN IN
TOP OF FENCE POST.


SECTION 5
T.8 S., R.13 E.

SECTION 4
T.8 S., R.13 E.

GURR ROAD

30'

30'



SCALE 1"=40'