


CORNER RECORD

Document Number 1363

City of \_\_\_\_\_

County of Merced, California

Brief Legal Description S.W. Corner Section 33, T. 7 S., R. 13 E., M. D. B. & M.



CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 8-02-07

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner – Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 2" Iron Pipe (I.D.), no tag, in monument well as referred to in Book 108 of Parcel Maps, Page 28, Merced County Records.

A description of the physical condition of the monument as found and as set or reset: Monument is in good condition. It will be destroyed by future road construction. See ties on page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on March 27, 2008

Signed [Signature] P.L.S or P.C.E. No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 27, 2008

and examined and filed April 1, 2008

Signed [Signature] P.L.S or P.C.E. No. 4895

Title Dep. County Surveyor



County Surveyor's Comment \_\_\_\_\_

SECTION 32  
T.7 S., R.13 E.

SECTION 33  
T.7 S., R.13 E.

CHISELED "X" IN  
CONCRETE WINGWALL.

FOUND 2" IRON PIPE IN MONUMENT  
WELL FOR S.W. CORNER OF  
SECTION 33 PER 108 PM 28.

DICKENSON

BRIDGE


FERRY ROAD

CHISELED "X" IN  
CONCRETE WINGWALL.

NAIL & TIN IN S.W.  
SIDE OF POWER POLE.  
SET NAIL AND TIN IN  
TOP OF FENCE POST.

SECTION 5  
T.8 S., R.13 E.

SECTION 4  
T.8 S., R.13 E.



SCALE 1"=40'

GURR ROAD

30'

30'

30'

30'

30'

30'

48.73'

43.70'

42.90'

58.13'