


**CORNER RECORD**

Document Number 2006-Y

City of \_\_\_\_\_

County of Merced, California

Brief Legal Description N.E. Corner of Santa Fe Drive & California Street intersection.



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 2-06-08

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner – Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Reestablished corner using ties shown on Merced County Corner Record No. 2006-Y dated March 27, 2008. Original monument destroyed by road construction. See page 2.

A description of the physical condition of the monument as found and as set or reset: Set 1" (I.D.) Iron Pipe with tag "Merced County Surveyor" in monument well.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 1, 2008

Signed [Signature] P.L.S. or ~~P.L.C.~~ No. 4895



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received April 1, 2008


and examined and filed April 1, 2008

Signed [Signature] P.L.S. or ~~P.L.C.~~ No. 4895

Title Dep. County Surveyor

County Surveyor's Comment See County Field Book 721, Page 41.





SCALE 1"=50'

CALIFORNIA STREET

LOT A  
68 O.P. 9

CHISELED "X" IN BACK OF  
CONCRETE SIDEWALK.

SET 1"(ID) IRON PIPE  
WITH TAG "MERCED COUNTY  
SURVEYOR" IN MONUMENT WELL.

NAIL & TIN ON SOUTHERLY  
SIDE OF POWER POLE, 2.5±  
ABOVE GROUND.

"PK" NAIL IN PAVE-  
MENT BETWEEN E.P.  
AND FOGLINE DESTROYED  
BY ROAD CONSTRUCTION.

"PK" NAIL IN PAVE-  
MENT BETWEEN E.P.  
AND FOGLINE.

ATCHISON - TOPEKA & SANTA FE RAILROAD

SANTA

FE

DRIVE

