


2156A

CORNER RECORD

COUNTY OF Merced T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []
CORNER IDENTIFICATION — DATE OF VISIT November 3, 19 76



West 1/4 corner Section 9.

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Monument was proportioned in from the Northwest Corner Section 9, 9/15 and the Southwest Corner Section 9, 9/15.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1" O.D. pipe with plastic plug marked L.S. 4156 at 0⁵ above ground line.
Also set two 1" O.D. pipes with plastic plug marked L.S. 4156 at ground surface. One 35.00 West on line and one pipe South 70.00 on line.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 77.21 Southeast from nail & shiner in power pole.
- 47.55 East from nail & shiner in concrete base of pump.
- 26.60 South from nail & shiner in fence post.
- 30.00 East from 1" O.D. pipe.
- 70.00 North from 1" O.D. pipe.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ONS. 4156 January 30, 19 79

SIGNED: [Signature] 4156
L.S. or R.C.E. No.:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____

DOCUMENT No. 2156A

STATEMENT ON BACK OF SHEET YES [] NO []