


2156

CORNER RECORD

COUNTY OF Merced T 9 S R 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEASURED [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION — DATE OF VISIT June 12, 1980



Northwest corner, Section 9

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1-1/2" O.D. cast cap on 5/8" rod marked L.S. 2737 @ 0.5 feet below ground line. Corner was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1" O.D. x 9" iron pipe tagged R.C.E. 12700 @ 0.8 feet below ground. Also set 1" O.D. x 28" pipe tagged R.C.E. 12700 @ 0.8 feet below ground 30 feet north on the section line.

** Pipe crossing below ground.


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 30.00 South of 1" O.D. pipe in fence corner.
15.38 East of lead plug in Southeast corner of outlet structure.
30.61 Northwest of lead plug in Southeast corner of inlet structure.
31.25 South of nail & shiner in railroad tie corner fence post.

SURVEYOR'S CERTIFICATE: THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 25 June

SIGNED: Frank C. Stamber No. 12700 L.S. or R.C.E. No.: 12700



COUNTY SURVEYOR'S CERTIFICATE: THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED BY: TITLE:

DOCUMENT No. 2156

STATEMENT ON BACK OF SHEET

YES [] NO []