


2157

CORNER RECORD

COUNTY OF Merced T 9 S. R 15 E. Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION -- DATE OF VISIT June 12 19 80



North quarter corner, Section 9.

CORNER -- LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

2-1/4" O.D. galvanized pipe tagged L.S. 2737 @ 0.8 feet below ground line. Monument was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Used swing ties to reset a 1" O.D. pipe @ 0.7 feet below ground line tagged R.C.E. 12700.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 33.44 Northeast from nail & shiner in utility pole.
- 45.58 Southeast from nail & shiner in railroad tie brace post.
- 28.12 South from nail & shiner in power pole.
- 26.98 West from lead plug in inlet structure. Plug 5.5 feet± South from headwall west side of structure.

SURVEYOR'S CERTIFICATE THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON June 25 19 80 No. 12700 SIGNED: Frank Stambaugh CIVIL ENGINEER L.S. or R.C.E. No. 12700



COUNTY SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____ BY: _____ TITLE: _____ DOCUMENT No. 2157 STATEMENT ON BACK OF SHEET YES [] NO []