

CORNER RECORD

Document Number 3655

City of _____ County of MERCED, California

Brief Legal Description SOUTH WEST CORNER SECTION 29 T.6S, R.10E., M.D.B&M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 7-20-94

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 1 1/4" IRON PIPE, ALSO FOUND 3/4" IRON PIPE WITH TAG. L.S. 3733 THAT IS 20' EAST OF 1 1/4" I.P.
CORNER ORIGIN CONCIDES WITH PARCEL MAP IN VOL. 65 PG. 96


A description of the physical condition of the monument as found and as set or reset: MONUMENTS IN GOOD CONDITION

POINT WAS TIED OUT PRIOR TO PAVEMENT PULVERIZATION PROJECT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 27, 1994.


Signed Roy L. Turney L.S. or ~~R.C.E.~~ Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 27, 1994 and examined and filed JULY 27, 1994.

Signed Roy L. Turney Title DEP. CO. SURVEYOR



County Surveyor's Comment _____



SEC. 30

SEC. 29

ROAD

FD. 1 1/4" I.P. S.W. COR
SEC 29 6/10

NAIL & SHINER IN OAK TREE

25.50'

FD. 3/4" I.P. L.S. 3733

20'

27.23'

NAIL & SHINER IN OAK TREE

SEC. 31

WASHINGTON

SEC. 32