


CORNER RECORD

Document Number 4116

City of _____

County of MERCED, California

Brief Legal Description S.E. COR. OF PARCEL 5 AS SHOWN ON "PARCEL MAP FOR THE NEWHALL LAND AND FARMING COMPANY" RECORDED IN BOOK 68 PAGE 27, SEC. 28 T.9S. R.13E.



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey Nov 9th 1999 Nov. 1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 3/4" IRON PIPE, TAGGED L.S. 3733, MONUMENT WELL SET OVER EXISTING MONUMENT.

A description of the physical condition of the monument as found and as set or reset:

MONUMENT WAS TIED OUT PRIOR TO A.C. OVERLAY & CHECKED UPON COMPLETION OF OVERLAY. SEE MAP OTHER SIDE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DEC. 1999

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JAN 2000

and examined and filed JAN 2000

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

Title Dep Co. Surveyor

County Surveyor's Comment _____



SECTION 28
T. 9 S., R. 13 E.



TO
TOP
OF
ROAD
LEVEL

STEEL PIPE
GATE POST
1' X ON EAST
SIDE OF POST

GATE

8" X 8" WOOD POST
SET NAIL 1/2 IN, S.E. SIDE
OF POST.

SET SPIKE, TEMPORARY
TIE DURING CONSTRUCTION

31.58'

65.37'

59.55'

WASHINGTON

ROAD

Fd. 3/4" IRON PIPE
SET MONUMENT ENCASEMENT
OVER PIPE. 75.64'

SET SPIKE,
TEMPORARY TIE
DURING CONSTRUCTION

SECTION 33
T. 9 S., R. 13 E.

TO
TOP
OF
ROAD
LEVEL