

# CORNER RECORD

Document Number 67  
 City of \_\_\_\_\_ County of MERCED, California  
 Brief Legal Description SECTION CORNER, SECTIONS 31&32, T5S R11E & SECTIONS 5&6, T6S R11E, MDM

T5S	R11E
S31	S32
S6	S5
T6S	R11E

### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey January 6-8, 2003

### COORDINATES(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Vert. Datum: NGVD29  NADV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET STANDARD CALIF. DOT 2 1/2" BRASS DISK FLUSH IN CONCRETE IN MONUMENT WELL  
DISK IS APPROXIMATELY 0.33' BELOW THE SURFACE OF BRADBURY ROAD. MONUMENT  
WAS RE-ESTABLISHED FROM TIES PER CORNER RECORD DOCUMENT NUMBER 67, DATED  
JUNE 23, 1998. MONUMENT HAD BEEN BURIED MORE THAN 20' BY FREEWAY  
CONSTRUCTION

A description of the physical condition of the monument as found and as set or reset: NEW

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyor's Act on January 8, 2003

Signed Robin L. Wickline P.L.S. or R.C.E. Number 7026  
 For the State of California  
 Department of Transportation




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 4, 2003 and examined  
 and filed FEB 28, 2003

Signed Roy L. Turney P.L.S. or R.C.E. Number 5523

Title Dep. Co. Surveyor  
 County Surveyor's Comment NONE



Ref: 7PM 36 MCR, CR 67, Dated June 23, 1998  
 12 PM 26 MCR, CR 67, Dated 9/22/92, Recorded 11/09/92  
 19 R/S 44 MCR Recorded 5/19/82

Legend

- Found Conc. nail w/brass tag "Cal Trans" 0.1' below A/C
- ◇ Set 2 1/4" Brass Disk flush in conc. in monument well

