

**CORNER RECORD**

Document Number 806

City of Planada

County of Merced, California

Brief Legal Description Intersection - Plainsburg Rd & Topeka St.



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner – Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/4" Iron Pipe, L.S. 3718 in monument well per corner record #806 dated 3-3-99

A description of the physical condition of the monument as found and as set or reset:

Set 3/4" Iron Pipe, L.S. 3733 in monument well from above reference after paving.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 8 2003

Signed [Signature] P.L.S or R.C.E. No. L.S. 3933

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received APRIL 10 2003

and examined and filed APRIL 29 2003

Signed [Signature] P.L.S or R.C.E. No. 5523

Title Dep. Co. Surveyor

County Surveyor's Comment \_\_\_\_\_

