

CORNER RECORD

Document Number 185

City of _____ County of MERCED, California

Brief Legal Description SW CORNER SECTION 32 10/10



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey 10-7-92

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 2" ID PIPE IN MONUMENT BOX.

A description of the physical condition of the monument as found and as set or reset: _____

OK. 8-30-93

F.B. 658-55

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 7 1992.


Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT 1993 and examined and filed SEPT 16, 1993.

Signed [Signature] Title DEP. CO. SUR.



County Surveyor's Comment _____

SEC 31

ROAD

SEC 32



SET 3/4" IP 35' N. OF FEN. COR.

STAND PIPE MARKED CANYON ORCHARD

35'
46.65'

SET PK NAIL IN TOP 6x8 POST

29.17'

6' CHAIN LINK

29.06'

FD SHINER S. SIDE P.P.

41.71'

SW COR. SEC. 32 10" FD 2" ID PIPE IN MON BOX NO LID. — New lid.

SET COTTON SPINDLE 33' S & 7' E OF FENCE COR. OPPOSITE GATE POST

GATE

SEC 5

SEC 6

CANYON

POINTS WERE TIED OUT PRIOR TO PAVING EFFORT BY MERCED COUNTY DEPARTMENT OF PUBLIC WORKS