


CORNER RECORD

Document Number 204

City of _____ County of Merced, California

Brief Legal Description North 1/4 Corner Section 13, T11S, R10E, MDB&M



11/10

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Oct. 26, 2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Original Corner was set on 8 R.S. 45 as South 1/4 Corner of Section 12, T11S, R10E. It was accepted as North 1/4 Corner of Section 13 on 96 P.M. 36 and 15 R.S. 2.

See sketch on back for procedure used to re-establish corner.


A description of the physical condition of the monument as found and as set or reset:

Set 1" (I.D.) Iron Pipe tagged "Merced County Surveyor".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 27, 2007

Signed [Signature] P.L.S or P.C.E. No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 27, 2007

and examined and filed December 28, 2007

Signed [Signature] P.L.S or P.C.E. No. 4895

Title Dep. County Surveyor



County Surveyor's Comment _____

