


**CORNER RECORD**

Document Number 235

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N.E. Corner Section 1 T9S R1E



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 4-26-91

**COORDINATES  
(Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 3/4" Iron Pipe, L.S. 3733. Monument well set over existing monument.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 10-1 1991.

Signed [Signature] L.S. or R.C.E. Number \_\_\_\_\_



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 10-2- 1991 and examined and filed 10-3 1991.

Signed [Signature] Title Dep Co Sur



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

