


CORNER RECORD

Document Number 272-D

City of _____

County of MERCED, California

Brief Legal Description THE CORNER COMMON TO LOTS 76, 77, 82, & 83 AS SHOWN ON MAP OF CROCKER FARMS UNIT TWO, RECORDED IN VOLUME 9 OF OFFICIAL PLATS, PAGE 13, M.C.R.



7/12

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Date of Survey NOVEMBER 2, 2010

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2 of 2

A description of the physical condition of the monument as found and as set or reset: _____

See Page 2 of 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the land Surveyors' Act on MARCH 10, 2011.

Signed Zachary T. Janz P.L.S. No.: 8664



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 29, 2011 and examined and filed April 4, 2011.

Signed J. Steven Reichmuth P.L.S. or ~~R.C.E.~~ No.: 4895

Title Deputy County Surveyor

County Surveyor's Comment _____





NORTH

0 100 200 300 400

SCALE: 1" = 400'

MORAN

AVENUE

LATERAL

B-1

77

76

FOUND ROTTING REDWOOD POST,
PER MAP OF CROCKER FARMS
UNIT TWO, 9 O.P. 13, M.C.R.,
SET 3/4" IRON PIPE, L.S. 8664.

MAP OF CROCKER FARMS
9 O.P. 13

81

83

82

McSWAIN

ROAD

140

STATE

HIGHWAY