


CORNER RECORD

Document Number 287

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N 1/4 Corner Section 4 T.7S., R.12E.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey 4-26-91
- Control
- Property
- Other

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 3/4" square rod, L.S. 3733. Monument well set over existing monument.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 10-1 19 91.


Signed Lawrence L. Bowers E.S. or R.C.E. Number \_\_\_\_\_



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10-2 19 91 and examined and filed 10-3- 19 91.

Signed Roy L. Turney Title Dep Co Sur



County Surveyor's Comment \_\_\_\_\_

SECTION

33

N.T.S.

Top of gate valve at center of stem.

CANAL

Nail & tin in transformer pole

91.09

54.90

23.10

Nail & tin in power pole

T6S R12E  
T7S R12E  
WEST SIDE

BLVD.

1/4 Corner  
Fd. 3/4" square rod in monument well.

50.01

STEINBURG ROAD

P.K. nail & tin between yellow stripes

SECTION

4

POINTS WERE TIED OUT PRIOR TO PAVING EFFORT BY MERCED COUNTY DEPARTMENT OF PUBLIC WORKS