


CORNER RECORD

Document Number 331

City of _____

County of MERCED, California

Brief Legal Description N.W. CORNER SECTION 6, T.9S., R.15E., M.D.B. & M.



T9S, R15E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12-19-2008

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2" I.D. IRON PIPE DOWN 1.1' PER CORNER RECORD 331
AND ADDED A COUPLE OF TIES.

CORNER MAY BE DESTROYED WITH CONSTRUCTION PROJECT

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 1 DEC. 22, 2008

Signed [Signature] P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 23, 2008

and examined and filed January 6, 2009

Signed [Signature] P.L.S. or R.C.E. No. 4895

Title Dep. Co. Surveyor



County Surveyor's Comment _____

