


331

CORNER RECORD

COUNTY OF Merced T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA
CORNER TYPE: GOVT. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []
CORNER IDENTIFICATION — DATE OF VISIT June 9, 1976



Northwest Corner Section 6.

CORNER — LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2-3/8" iron pipe at 10" below road surface with redwood plug.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1" x 2" stake at road surface.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 26.26 South from nail & shiner in power pole.
- 37.25 Southwest from nail & shiner in power pole.
- 40.25 Northeast from nail & shiner in power pole.
- 92.62 Northeast from nail & shiner in power pole.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 4156 January 30, 1979

SIGNED: *Johnny E. Davis*
L.S. No. 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____

TITLE: _____

DOCUMENT No. 331

STATEMENT ON BACK OF SHEET

YES [] NO []