


#333

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E Mt. Diablo MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION -- DATE OF VISIT June 24, 1980



Northwest corner Lot 8, Block 18 (Section 18) of the Bliss Ranch Subdivision on file in Volume 7, Page 40, M.C.R.

CORNER -- LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

2-1/4" O.D. pipe @ 1.55 below road surface.
 Corner was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Reset from swing ties.
 Set 1" O.D. x 14" ** iron pipe tagged R.C.E. 12700 @ road surface.


** pipe crosses below ground.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 51.68 Southwest from nail & shiner in power pole.
- 56.63 East from nail & shiner in power pole.
- 82.15 Northeast from nail & shiner in power pole.

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON 25 June No. 12700
 SIGNED: Frank S. Stambold
 L.S. or R.C.E. No. 12700



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____
 BY: _____
 TITLE: _____
 DOCUMENT No. 333
 STATEMENT ON BACK OF SHEET

YES NO