


CORNER RECORD

Document Number 347

City of _____ County of MERCED, California

Brief Legal Description SOUTH WEST CORNER SECTION 1 T.8S., R.14 E., M.D. B&M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 7-14-94

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2" IRON PIPE 0.5' DOWN S.W. CORNER SECTION 1, ALSO FOUND 1 1/4" IRON PIPE WEST, 108.27' AT THE INTERSECTION OF S. ORCHARD DRIVE CORNER ORIGIN CONCIDES WITH RECORD OF SURVEY MAP VOL. 23 PG 11 AND CO. FIELD BK 709 PG. 57


A description of the physical condition of the monument as found and as set or reset: MONUMENTS IN GOOD CONDITION

POINTS WERE TIED OUT PRIOR TO PAVEMENT PULVERIZATION PROJECT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 15 1994.

Signed Roy L. Turney L.S. or ~~R.C.E.~~ Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 15 1994 and examined and filed JULY 15 1994.

Signed Roy L. Turney Title DEPUTY COUNTY SURVEYOR
 County Surveyor's Comment _____

