


CORNER RECORD

Document Number 357

City of _____ County of Merced, California

Brief Legal Description Southwest Corner Section 18, T. 8 S. R. 9 E., M. D. B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 09-12-2013

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4" OD IP w/YPP "unreadable" down 1.0'. Inside 2" IP per
Parcel Map vol. 104, pg. 17, & Record of Survey vol. 51, pg. 36.

A description of the physical condition of the monument as found and as set or reset: Monument was found in
good condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on September 24, 2013
Signed Bradley D. Bulter P.L.S or R.C.E. No. L7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 1, 2013
and examined and filed October 7, 2013
Signed [Signature] P.L.S or R.C.E. No. 4895
Title County Surveyor



County Surveyor's Comment _____



WHITWORTH ROAD

TO SR 140

FND NAIL & SHINER
IN UTILITY POLE

FND NAIL & SHINER
IN UTILITY POLE

FND NAIL & SHINER
IN UTILITY POLE
CUT 6' TALL

81.71'

GUN CLUB ROAD

TO SR 33

34.63'

FD 3/4" OD IP
W/YELLOW PLUG
(UNREADABLE) DOWN 1.0'

46.76'

SET REBAR W/PUNCH
6.7' FROM EP DOWN 0.3'

