

CORNER RECORD

Document Number 381(2)

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description SW Corner Section 18; T.8 S., R. 14 E., M. D. B. & M.



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey August 4, 2014

COORDINATES (Optional)

N \_\_\_\_\_  
E \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found monument at C/L McNamara Rd. and HWY 59. Monument is an 1 3/4" O.D. Iron Pipe, (1 1/4" I.D. per record), down in concrete 0.96' below AC surface. No Tag recovered.  
Map Reference: Merced County Corner Record #381, November 30, 1994

A description of the physical condition of the monument as found and as set or reset: Monument found in good condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 2 2014

Signed Bradley D. Buller P.L.S. or R.C.E. No. L7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 9, 2014  
and examined and filed Sept. 15, 2014

Signed J & B P.L.S. or ~~R.C.E.~~ No. 4895

Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



SET  
PK NAIL WITH CALTRANS  
BRASS TAG  
NE'LY SIDE  
OF POWER POLE,  
No.  $\frac{2}{16}$

37.73'

FD  $1\frac{3}{4}$ " O.D.  
IRON PIPE  
DOWN 0.96' NO TAG  
SET IN CONCRETE

47.83'

SET  
 $\frac{5}{8}$ " REBAR IN  
DIRT, DOWN 0.3',  
SIDE EDGE OF  
DRIVEWAY DITCH

TO EL NIDO

STATE ROUTE

59

TO MERCED

56.30'

SET  
PK NAIL WITH CALTRANS  
BRASS TAG  
NE'LY SIDE  
OF POWER POLE

57.78'

FD  
CALTRANS "C" MON  
WITH IRON PIN  
FLUSH WITH TOP

84.65'

CHISLED "X" WITH  
PUNCH MARK  
IN CENTER OF HEAD WALL

MCNAMARA RD

