


CORNER RECORD

Document Number 591 U

City of _____ County of MERCED, California

Brief Legal Description S.W. COR. LOT 19 AS SHOWN ON MAP OF MORAN COLONY, RECORDED IN VOL 7, PAGE 57, OFFICIAL PLATS, MERCED COUNTY REC.



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey _____

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND ROTTEN REDWOOD - SET 3/4" INSIDE DIAMETER IRON PIPE IN CENTER WITH LS 7621 TAG. CHECKED DIST. EAST, WEST & NORTH. (SEE BACK)

A description of the physical condition of the monument as found and as set or reset: FOUND ROTTEN 4x4

RED WOOD - SET 3/4" INSIDE DIAMETER IRON PIPE IN CENTER WITH LS 7621 TAG.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on SEPT. 21, 2000

Signed David Heinrichs P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received OCT 2000

and examined and filed NOV. 14, 2000

Signed Roy L. Turney P.L.S. or R.C.E. No. 5523

Title Roy L. Turney - DEP. CO. SUR.

County Surveyor's Comment _____





MORAN

ROAD

