


CORNER RECORD

Document Number 828-X

City of _____

County of Merced, California

Brief Legal Description GPS Control Point



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 09-12-2013

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 2" aluminum disk atop rebar on centerline of SR 140/Sullivan Road at Prince Road down 0.4' as per RS Volume 28 Pages 15-16, and Subdivision Map Volume 44 Page 49, Sheet 2 of 4, in 1' diameter well.

A description of the physical condition of the monument as found and as set or reset: Monument was found in good condition. Information on disk reads "GPS/GIS 2005 RCE (mashed)".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 24, 2013
Signed Bradley Buller P.L.S or R.C.E. No. L7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 1, 2013
and examined and filed October 7, 2013
Signed J. Steven Reichmuth P.L.S or ~~R.C.E.~~ No. 4895
Title County Surveyor



County Surveyor's Comment _____



NTS

