


# CORNER RECORD

COUNTY OF MERCED, CALIFORNIA

SECTION 7 TOWNSHIP 7 RANGE 13 EAST M.D.B. & M.

BRIEF LEGAL DESCRIPTION: NORTHEAST CORNER SECTION 7



CORNER TYPE:

COORDINATES

GOV'T CORNER  CONTROL  N. \_\_\_\_\_  
 MEANDER  PROPERTY  \_\_\_\_\_  
 RANCHO  OTHER  ZONE \_\_\_\_\_

DATE OF SURVEY: 4-SEPT-91 ELEV. \_\_\_\_\_

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE USED TO IDENTIFY THE CORNER  
FOUND 2" IRON PIPE FOR 1/4 CORNER SECTION 7 DESTROYED BY CONSTRUCTION

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT, PERPETUATED, OR RESET  
SET 3/4" IRON PIPE WITH PLUG RCE 29547 IN MONUMENT WELL  
REPLACING FD. 2" IRON PIPE

**SURVEYOR'S STATEMENT**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEBRUARY 18 19 93

SIGNED: Randall A. O'Dell

L.S. OR R.C.E. NO. 29547 EXPIRES 3/31/95


**COUNTY SURVEYOR'S STATEMENT**

THIS CORNER RECORD WAS RECEIVED 2-22 19 93

AND EXAMINED AND FILED 2-24 19 93

BY: Roy L. Turney

TITLE: Deputy County Surveyor



YES  NO  SKETCH ON BACK OF SHEET

COUNTY SURVEYOR'S STATEMENT: Monument agrees with Price  
Subdivision Vol 38 A.P. Page 38 and other records

# CORNER RECORD

SKETCH (Include reference file or witness points, remarks and topo of area)

N 21 123 25 124 640-00-00

ALT : 2292  
TEMP : 82°

G. Wiseman  
M. 283A  
4 Sept 1991

3

PT	4 RT	HD
122	89 41 19	35.000
1/2 IP	187 03 17	69.469
1/2 IP	287 03 47	128.110
1/2 IP	287 03 17	176.525

