


CORNER RECORD

Document Number 1057-Z

City of MERCED

County of MERCED, California

Brief Legal Description LINE BETWEEN LOTS 62 & 63 of 20 O.P. 49-54, M.C.R.



T. 17 S., R. 13 E.

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 3/4" IRON PIPE AT BOTH CORNERS W/ R.C.E. 6888 TAG -
SET TIES TO RELOCATE CORNERS IF DESTROYED BY CONSTRUCTION
OF STORM DRAIN PIPE.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JANUARY 31, 2002

Signed David D. Heinrich P.L.S. or R.C.E. No. 7621




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-6-02

and examined and filed 2-6-02

Signed Roy L. Turney P.L.S. or R.C.E. No. 5529

Title DEP. CO. SURVEYOR



County Surveyor's Comment NONE

