

CORNER RECORD

Document Number 1249

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description Southeast Corner Section 11, T. 8 S. R. 8 E., M. D. B. & M.



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey April 16, 2014

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 2" Brass disk in in 6" metal sleeve down 0.95' as per  
PM Vol. 50 Page 15 and PM Vol. 100 Page 43.

A description of the physical condition of the monument as found and as set or reset: Monument was found in  
good condition. Information on disk is unreadable.  
1' diameter well set during repaving.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on May 13 2014  
Signed Bradley D. Buller P.L.S or R.C.E. No. L7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 20, 2014  
and examined and filed May 22, 2014  
Signed [Signature] P.L.S or R.C.E. No. 4895  
Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



SCHMIDT ROAD

SULLIVAN ROAD

SR 140

TO I-5

TO GUSTINE

FND 2" PIPE  
DOWN 1.5'



39.70'

FND NAIL & SHINER  
IN UTILITY POLE



72.32'

FND NAIL & SHINER  
IN UTILITY POLE



61.53'

FND 2" BRASS DISK  
IN 6" METAL SLEEVE  
SET INSIDE 1' DIAMETER  
MONUMENT WELL DOWN 1.0'



FND NAIL & SHINER  
IN UTILITY POLE



37.51'

SET PK WITH BRASS  
CALTRANS WASHER  
IN UTILITY POLE



107.13'