


CORNER RECORD

Document Number _____

City of _____ County of MERCED, California

Brief Legal Description N.E. COR. SECT. 7 T.9S.R.9E., MDB&M



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1-4-90

**COORDINATES
(Optional)**

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 1 1/2" IRON PIPE, NO ORIGINAL COUNTY TIES REMAIN, POINT FALLS IN APPROXIMATE CENTER OF INTERSECTION.

A description of the physical condition of the monument as found and as set or reset: MONUMENT IS DOWN 1" AND APPEARS TO BE IN GOOD CONDITION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JAN 4 1990.


Signed [Signature] L.S. or R.C.E. Number LS3730

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-24 1990 and examined and filed 1-25- 1990.

Signed [Signature] Title Dep. Co. Surveyor COR. # 1251

County Surveyor's Comment _____



1251

6	5
7	8

T9SR9E
MDB&M

