


Brief Legal Description SOUTHWESTERLY CORNER OF PARCEL "A" OF 35 PM 9. M.C.R.



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 3-22-96

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish the corner:  
FOUND PROPERTY CORNER PER BOOK 35 OF PARCEL MAPS AT PAGE 9. M.C.R.

A description of the physical condition of the monument as found and as set or reset:  
FOUND 1-1/2" IRON PIPE FLUSH. NO TAG. LEFT AS FOUND


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 27 1996.  
Signed [Signature] L.S. or R.C.E. Number L.S. 5503



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 1996 and examined and filed MAY 21 1996.  
Signed [Signature] Title DEP CO. SUR.



County Surveyor's Comment \_\_\_\_\_

