


CORNER RECORD

Document Number 1423

City of _____ County of MERCED, California

Brief Legal Description NORTH EAST CORNER SECTION 14 T. 7S., R. 10E. M.D.B. & M



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey FEB. 2, 2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND CONCRETE MONUMENT WITH 3/8" IRON PIN IN CENTER

A description of the physical condition of the monument as found and as set or reset: MONUMENT WAS TIED OUT PRIOR TO ROAD CONSTRUCTION AND RESET WITH WITH TIES SHOWN ON BACK (SEE BACK FOR SKETCH) WITH 1" IRON PIPE TAGGED MERCED COUNTY SURVEYOR IN SURVEY ENCASEMENT.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MARCH 3 2001

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 3, 2001

and examined and filed APRIL 30, 2001

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

Title DEPUTY CO. SURVEYOR

County Surveyor's Comment _____

