

**CORNER RECORD**

Document Number 1906

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description Southwest Corner Section 11, T. 8 S. R. 8 E., M. D. B. & M.



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey April 16, 2014

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 2" Brass Disk (Division of Highways) with punch mark down 0.9' in 6" monument well per Parcel Map 100 Page 43.


A description of the physical condition of the monument as found and as set or reset: Monument was found in good condition. 1' diameter well set during repaving.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MAY 13 2014

Signed Bradley D. Buller P.L.S. or R.C.E. No. L7659



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received May 20, 2014

and examined and filed May 22, 2014

Signed [Signature] P.L.S. or R.C.E. No. 4895

Title County Surveyor

County Surveyor's Comment \_\_\_\_\_





ORCHARD ROAD

SULLIVAN ROAD

SR 140

TO I-5



TO GUSTINE



SET PK WITH BRASS  
CALTRANS WASHER  
IN UTILITY POLE

42.97'

FND 2" BRASS DISK  
IN 6" METAL SLEEVE  
SET INSIDE MONUMET  
WELL DOWN 0.9'

56.22'

SET PK WITH BRASS  
CALTRANS WASHER  
IN UTILITY POLE

85.27'

FND US COAST & GEOD.  
SURVEY BENCH MARK  
"Y1127 1961"