


CORNER RECORD

Document Number 1956

City of _____ County of Merced, California

Brief Legal Description Northeast Corner Sec. 16, T. 8 S. R. 8 E., M. D. B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey April 16, 2014

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner - Left as found. Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 2" Brass Disk with punch mark down 1.8' in Monument well per PM vol. 6 - page 29, PM vol. 16 - page 24 and PM bk. - 7 page 2.

A description of the physical condition of the monument as found and as set or reset: Monument was found in good condition. 1' diameter well set during repaving.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Mar 13 2014
Signed Bradley D. Buller P.L.S or R.C.E. No. L7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 20, 2014
and examined and filed May 22, 2014
Signed [Signature] P.L.S or R.C.E. No. 4895
Title County Surveyor



County Surveyor's Comment _____



FND NAIL IN TOP OF 6" ROUND
4' HIGH FNC COR POST

TO I-5 NB ON RAMP

SET CHISELED "T"
TOP OF CURB

52.16'

52.28'

FND 2" BRASS DISK
WITH PUNCH MARK
IN MONUMENT WELL
DOWN 1.9'

SULLIVAN ROAD
SR 140

35.63'

SET CHISELED "T"
TOP OF CURB

61.29'

TO GUSTINE

SET CHISELED "T"
TOP OF CURB

