


CORNER RECORD

Document Number 2002

City of _____ County of MERCED, California

Brief Legal Description _____



6/12

CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey 3-9-95
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
On or near centerline El Capitan Road - Do not know where corner came from.

A description of the physical condition of the monument as found and as set or reset: Fd. Lag bolt with 1 1/2" top and punched "t", found 2x2" below, found 2nd 2x2" lying on side, dug to 2⁵. We suspect that the bolt is out of position by 0.27'S. & 0⁶W.
Set 3/4" Iron pipe, L.S. 4403 in Monument Well (10-20-95)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct 24 1995.


Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 1995 and examined and filed NOVEMBER 30 1995.

Signed [Signature] Title DEP CO. SUR.



County Surveyor's Comment History of monument suggests monument may not be in true location at Section Cor. See County field Book 46 Page 35 for history.

