


# CORNER RECORD

Document Number 2013

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N 1/4 Corner Section 22 T11S R10E



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 3-26-90

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

NOTE: There are 2 corners, both are correct. Both corners are 1 1/2" iron pipes. Monument well set over existing monuments.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 10-1 1991.

Signed [Signature] L.S. or R.C.E. Number \_\_\_\_\_



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10-2- 1991 and examined and filed 10-3- 1991.

Signed [Signature] Title Dep Co Sur



County Surveyor's Comment \_\_\_\_\_

NOTE: Double 1/4 Corner, both correct.

SECTION

15

Nail 4 tin in power pole.

S 1/4 Corner Section 15  
Fd. 1 1/2" Iron Pipe in  
monument well.

MERVEL

43° 51' 00" Z

AVENUE

N. W. Corner Section 22

N 1/4 Corner Section 22  
Fd. 1 1/2" Iron Pipe in  
monument well.

3/4" Iron Pipe, L.S. 3733

SECTION

22

N.T.S.

1/4 Section Line

POINTS WERE TIED OUT PRIOR TO PAVING  
EFFORT BY MERCED COUNTY DEPARTMENT  
OF PUBLIC WORKS