


CORNER RECORD

Document Number 2022

City of _____ County of Merced, California

Brief Legal Description S.E. Corner Section 28, T.10 S., R.10 E.



10/10

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey May 11, 2012

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1 1/2" Iron Pipe, No tag, in monument well. Accepted as S.E. corner of Section 28, T.10 S., R.10 E. by 44 R.S. 47 and 110 P.M. 32.

A description of the physical condition of the monument as found and as set or reset: See Page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on June 5, 2012.
Signed J. Steven Reichmuth P.L.S. or P.C.E. No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 5, 2012
and examined and filed June 5, 2012
Signed J. Steven Reichmuth P.L.S. or P.C.E. No. 4895
Title Acting County Surveyor



County Surveyor's Comment _____

