

CORNER RECORD

Document Number 2031

City of _____ County of MERCED, California

Brief Legal Description EAST 1/4 CORNER SECTION 16, T16S. R. 10E



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2" IRON PIPE 20" below surface in Monument Well Raised to Surface with 5/8" rod & County Surveyor cap
SEE PARCEL MAP BOOK 28 PAGE 47


Point tied out prior to paving effort by Merced County

A description of the physical condition of the monument as found and as set or reset: These ties are for the purpose of perpetuating the monumentation. No claim is made as to the relationship of the points or lines shown hereon to the true boundary locations

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 14 1995.


Signed Roy L. Turney L.S. or R.C.E. Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 1995 and examined and filed OCTOBER 16, 1995.

Signed Roy L. Turney Title DEP. CO. SURVEYOR



County Surveyor's Comment _____

