


**CORNER RECORD**

Document Number 2243

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description PROPERTY CORNER ON N. LINE OF SEC. 1, T. 9 S., R. 14 E., M.D.B. & M.



T9S, R14E

**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 12-19-2008

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND 1" I.D. IRON PIPE DOWN 1', 2077' WEST ON N.E. CORNER OF SEC. 1, 4.2' N. OF EDGE OF PAVEMENT. MONUMENT IS SHOWN ON 42 R.S. 19 AND SURVEYOR'S FILE No. 1-F-5.

MAY BE DESTROYED WITH CONSTRUCTION PROJECT

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DEC. 22, 2008

Signed [Signature] P.L.S. or R.C.E. No. 7621



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received December 23, 2008


and examined and filed January 6, 2009

Signed [Signature] P.L.S. or R.C.E. No. 4895

Title Dep. Co. Surveyor

County Surveyor's Comment \_\_\_\_\_





SCALE 1" = 20'

