


CORNER RECORD

Document Number 2284

City of _____

County of Merced, California

Brief Legal Description S 1/4 Corner Section 28 10/10



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 8-14-92

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset: _____

Ed. 1 1/4" brass cap

Monument well set over existing monument. 8-24-93

F.B. 658-29

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 7 19 93.


Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT 19 93 and examined and filed SEPT 16 19 93.

Signed [Signature] Title DEP. CO. SUR.



County Surveyor's Comment _____

SEC 28

CORN FIELD

CHIS "+" ON E. SIDE
OF CONC. STANDPIPE
(36" ID)

FD. NAIL & BOTTLE CAP
IN E. SIDE POWER POLE



FD. 1 1/4" DIA. BRASS CAP
FLUSH WITH ROAD.
(NO STAMPING OR PUNCH
HOLE; USE E AS REF. PT.)

1/2 MILE orthogonal

Monument well set over
brass cap.

SUNSET AVENUE

28.29'

34.24'

51.29'

SET 3/4" IP, DOWN 1", NO TAG;
IN POLE LINE SOUTH.
OPPOSITE TELE. POLE.

SET NAIL & SHINER IN
SW SIDE TELE. POLE

DIRT RD.

COTTON

COTTON

SEC 33

POINTS WERE TIED OUT PRIOR TO PAVING
EFFORT BY MERCED COUNTY DEPARTMENT
OF PUBLIC WORKS