

2381P

COLLAR RECORD

COUNTY OF Merced T. 10S R. 14E M.D.B. & M. MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT January 19.78



60 ft. North of 1/16 corner

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found and tagged L.S. 4156 a 2" iron pipe @ 4.0 ft. below groundline.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 60.00 ft. North of N.W. corner of N.E. 1/4 of N.W. 1/4, Section 5, 10/14
- 46.30 ft. Southeast of 60^D nail & shiner in top of fence post
- 20.00 ft. South of 60^D nail & shiner in top of corner r.r. tie fence post
- 5.85 ft. Northeast of 60^D nail & shiner in top of fence post



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON June 14 1978

SIGNED: *Johnny E. Davis*
L.S. or R.C.E. No.: L.S. 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19. _____
AND EXAMINED AND FILED _____ 19. _____

BY: _____
TITLE: _____

DOCUMENT No. 2381A

STATEMENT ON BACK OF SHEET

YES NO