


CORNER RECORD

Document Number 2405

City of _____ County of Merced, California

Brief Legal Description S.W. Section 29 10/10



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-3-92

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset: _____

Fd. 2" Iron Pipe, R.C.E. 13760, Monument box OK. 8-21-93

F.B. 658-43

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 7 19 93.


Signed Lawrence L. Bowers L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT. 19 93 and examined and filed SEPT. 16 19 93.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

SEC 30

SEC 29

FD. NAIL & BOTTLE
CAP E. SIDE P.P.

SET NAIL & SHINER NW
SIDE OF P.P.

SET NAIL & SHINER
IN S. SIDE P.P.

ROAD

59.73'

49.83'

64.77'

SUNSET
AVENUE

SET 3/4" IP W/BLANK
(YELLOW) TAG IN
POLE LINE N.

30.11'

P.P. NW CORNER SEC. 32.
T. 10S., R. 11E. FD. 2" ID
PIPE IN MON BOX TAG
RCE 13760 NO LID.

CANYON



SEC 31

SEC 32

POINTS WERE TIED OUT PRIOR TO PAVING
EFFORT BY MERCED COUNTY DEPARTMENT
OF PUBLIC WORKS