

2443

CL. RECORD

COUNTY OF Merced T. 10S R. 14E M.D.B. & M. MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT January 19 78



Northwest corner

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found and tagged L.S. 4156, a 5/8" steel rebar @ 0.1 feet below road surface

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 30.00 ft. South of intersection of Orchard Way and Jefferson Road
- 26.53 ft. Southwest of nail & shiner in 4" x 6" post
- 72.63 ft. Southwest of nail & shiner in power pole
- 67.20 ft. Southwest of 2" O.D. pipe in fence corner



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JUNE 14 19 78 L.S. 4156
SIGNED: Johnny E. Davis
of R.C.E. No. 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____
AND EXAMINED AND FILED _____ 19 _____
BY: _____
TITLE: _____
DOCUMENT No. 2443 2387
STATEMENT ON BACK OF SHEET YES NO