


CORNER RECORD

Document Number 2562-C

City of Stevenson County of Merced, California

Brief Legal Description Boundary Corner; at N'ly terminous of 19' course on 44 RS 30, MCR.



S10, T7S, R10E MDM

CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey May 19, 2014

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.  
Found 2" Iron Pipe; no tag, Boundary Corner per 44 RS 30, MCR.  
Set ties as depicted on the reverse page.

A description of the physical condition of the monument as found and as set or reset: Found 2" monument down 1.0',  
rusted - good condition, straight.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on June 25, 2014  
Signed [Signature] P.L.S or R.C.E. No. LS6646



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 25, 2014  
and examined and filed July 10, 2014  
Signed [Signature] P.L.S or ~~R.C.E.~~ No. 4895  
Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



GRAPES

SET  
PK NAIL WITH CALTRANS  
BRASS TAG; SE'LY SIDE  
OF POWER POLE,  
No.4106

TO HILMAR

165

ROUTE

STATE

239.22'

SET  
CHISELED " X " ON  
E'LY SIDE, 1.95' S'LY  
FROM NE CORNER  
OF BOX.



44.15'

FD 2" IRON PIPE  
DOWN 1.0'  
NO TAG



98.18'



SET  
CHISELED " X " "  
AT NW'LY CORNER,  
IRRIGATION CONCRETE  
BOX.

Tare Station



Shack



72.40'

Entry to Arthur  
Oliveira Dairy

TO LOS BANOS

SET  
CHISELED "X" AT HALF WAY  
POINT ON ARC OF IRRIGATION GATE.