


CORNER RECORD

Document Number 2699

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N.E. COR SEC. 27, T.10 S. R.10 E



CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Monument agrees with P.M. BK. 80 PG. 45 & P.M. BK. 22 Pg. 31  
FD 2" I.P. WITH CAP. (SEE REVERSE SIDE FOR SWING TIES)  
POINT TIED OUT NOVEMBER 1996 PRIOR TO PAVING EFFORT BY MERCED  
COUNTY (MONUMENT WELL SET AFTER PAVING)

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR  
THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM  
IS MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN  
HEREON TO TRUE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.


Signed Roy L. Turney L.S. or R.C.E. Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_

OK. 1-14-97

