


**CORNER RECORD**

Document Number 2840 (2)

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description S.E. Section Corner, Sec. 35 T.9S.R.10E., M.D.M.&B.



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 02-08-2013

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found 2.25" Brass Disk with no markings in concrete down 0.6' in monument well. Monument is in the intersection of SR-165 and Henry Miller Ave per corner record #2840.

A description of the physical condition of the monument as found and as set or reset: Monument found in good condition.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on MARCH 21 2013

Signed Bradley D. Buller P.L.S. or R.C.E. No. L 7659



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received March 21, 2013

and examined and filed April 4, 2013

Signed J. Steven Reichmuth P.L.S. or R.C.E. No. 4895

Title Acting County Surveyor

County Surveyor's Comment \_\_\_\_\_



35 36

T9S R10E

MDB&M

2 1

T10S R10E

