


**CORNER RECORD**

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description E 1/4 COR. SECT. 2 T10S R10E M0B&M



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 1-3-90

**COORDINATES  
(Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: BRASS DISK IN MONUMENT WELL - DOWN 05

STAMPED USBR 2/1 1965

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

APPEARS IN GOOD CONDITION

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JAN 3 1990.


Signed Ralph Schulf. L.S. or R.C.E. Number LS9730

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 1-24 1990 and examined and filed 1-25 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor COR. # 2841

County Surveyor's Comment \_\_\_\_\_



# 2841

2 • 1 TIOSRIOE  
MOBEM

