


CORNER RECORD

Document Number 2995

City of _____

County of MERCED, California

Brief Legal Description NORTH 1/4 CORNER OF SECTION 10, T.11 S., R.12 E., M.D.B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey MAY 9, 2013

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 1" IRON PIPE 2" DOWN. SET FOR THE NORTH 1/4 CORNER OF SECTION 10 PER 4 R.S. 42.
MONUMENT TIED OUT PRIOR TO OVERLAY OF REYNOLDS AVENUE.


A description of the physical condition of the monument as found and as set or reset: SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Sept. 30, 2013

Signed [Signature] P.L.S or ~~P.E.~~ No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 30, 2013

and examined and filed Sept. 30, 2013

Signed [Signature] P.L.S or ~~P.E.~~ No. 4895

Title County Surveyor



County Surveyor's Comment _____

C.R. # 2995

