


**CORNER RECORD**

Document Number 3025

City of \_\_\_\_\_ County of MERCED California

Brief Legal Description N.E. COR. SECT 22, T10S R1E MDBEM



**CORNER TYPE**

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 6-29-90

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 2X2 HUB & NAIL DOWN 0.6 PER STATE HWY MAP 10-MER 152 PG. 10 OF 47

A description of the physical condition of the monument as found and as set or reset: HUB & NAIL IN GOOD CONDITION - SET 2' RPS & 1' PR AT SURFACE

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 29 1990.

Signed Ralph N. Scheel L.S. or R.C.E. Number LS3730



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment COR. # 3025

15

14

TIOSRHE  
MOBEM

22

23

