


CORNER RECORD

Document Number 3030

City of _____ County of MERCED; California

Brief Legal Description N.E. COR SECT. 25, T.10S., R.11E., MOBEM.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6-18-90

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND ^{good nail} ~~REDWOOD POST~~ WITH PLASTIC PLUG DOWN $2\frac{1}{2}$ " FROM OLD CALTRANS SWING TIES. RESET 2.00' RPS NE'W 47PM 87

A description of the physical condition of the monument as found and as set or reset: NAIL & PLUG IN GOOD CONDITION - DID NOT DIG FOR PIPE OR REDWOOD POST.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 18 1990.

Signed Ralph M. Scheel, Jr. L.S. or R.C.E. Number LS. 3730
 Lic. Exp. 6-30-92



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment COR. # 3030

T105 R116	T105 R126	MDB&M
24	19	
25	30	

