


CORNER RECORD

Document Number 3032-G

City of _____ County of MERCED, California

Brief Legal Description PROPERTY CORNER ON 1/4 LINE 1140.46' S OF N 1/4 COR SEC 20 T10S R12E MDM



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6-15-90

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 3/4" I. PIPE PLUGGED LS 4156 PER 35 PM 33 & 7RS35

A description of the physical condition of the monument as found and as set or reset: MOVEMENT IS IN GOOD CONDITION, DOWN 0.8"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 15 1990.

Signed Ralph N. Scheel, Jr. L.S. or R.C.E. Number LS 3730
 Lic. Exp. 6-30-90



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment COR. NO. 3032 G

17
20

T105 R 12E
MOBEM

ST. RT. 152

17
20
Fd. nail
SET SPIKE

1140.46 (R)
78535

CHARLUCCI

SET PRESSURE IN
J POLE

Fd. 3/4" I.P. PIPE lagged
LS 4156, DOWN 0⁸
TR535 - 35PM33

ROAD