


CORNER RECORD

Document Number 3032

City of _____ County of MERCED, California

Brief Legal Description N.E. COR. SECT. 19, T10S R12E, MDB&M



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6-27-90

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: SEARCHED - FOUND NOTHING - DUG TO OLD CONCRETE ROAD - SET SPIKE AT SURFACE PER SRS40

A description of the physical condition of the monument as found and as set or reset: SPIKE AT SURFACE NEAR WHITESTRIPE OF WESTBOUND LANES.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 6-27 1990.

Signed Ralph N. Scheel, Jr. L.S. or R.C.E. Number 653730



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor

County Surveyor's Comment COR. No. 3032 OK



18'17
19'20
TOSR 12E
MDCM

